

PHDM16-00002

Date: July 25, 2016

Application Type: Certificate of Appropriateness

Property Owner: Kahlo 1 LLC **Representative:** Raymundo Ramos

Legal Description: 17 Sunset Heights 20 & N 15 Ft Of 19 & S 5 Ft Of 21, City of El Paso, El

Paso County, Texas

Historic District: Sunset HeightsLocation: 1401 Randolph Drive

Representative District: #8

Existing Zoning: R-4/H (Residential/Historic)

Year Built: 1906

Historic Status: Contributing

Request: Certificate of Demolition for the demolition of a rear yard structure after-

the-fact

 Application Filed:
 7/11/2016

 45 Day Expiration:
 8/25/2016

ITEM #6



GENERAL INFORMATION:

The applicant seeks approval for:

Certificate of Demolition for the demolition of a rear yard structure after-the-fact

STAFF RECOMMENDATION:

The Historic Preservation Office recommends DENIAL of the proposed scope of work based on the following recommendations:

The Design Guidelines for El Paso's Historic Districts, Sites, and Properties recommend the following:

- Secondary buildings are structures which are detached from the primary structure.
 They were traditionally used as garages, stables, kitchens, caretaker cottages and
 privies. These structures were usually built at the same time and therefore are very
 important to the architectural character of the property.
- It is not appropriate to introduce prefabricated metal accessory structures in the historic districts.
- Once a property is demolished it is gone forever and can never be replaced. It is rarely appropriate to demolish a historic structure unless it has suffered severe and irreparable damage.

The Secretary of the Interior's Standards for Rehabilitation recommend the following:

- The historic character of a property shall be retained and preserved. The removal of historic materials or alteration of features and spaces that characterize a property shall be avoided.
- Most properties change over time; those changes that have acquired historic significance in their own right shall be retained and preserved.
- When the severity of deterioration requires replacement of a distinctive feature, the
 new feature will match the old in design, color, texture, and where possible materials.
 Replacement of missing features shall be substantiated by documentary, physical, or
 pictorial evidence.

AERIAL MAP



SITE PLAN 10.6 45.00 0.9 000 COVD CONC CONCRETE HEADER (TYPICAL) ROCKWALL (TYPICAL) 1401 RANDOLPHI 68.99 STREET LOT 21 2,8 55 2,6 0 0 515 9.6 55 83T8'35" OF STUSTING 1.0' -STUCCO 3.21 BUILDING. BLDG 8.1 0.2 4.0 r S 2 3.4 15' ALLEY SO SHIFTIGHED ON SCALE 1"=20" COPYRIGHT (2003 CAD CONSULTING CO. ALL RIGHTS RESERVED JOB # 233047 DATE: 10-24-03 FIELD: RF OFFICE: EA FILE: NET:ENRIQUE\2003\233047 CERTIFICATION LOCATED IN ZONE PANEL # 480214-0033-B DATED 10-15-82 I HEREBY CERTIFY THAT THE FORECOING BOUNDARY SURVEY WAS MADE ON THE GROUND AND UNDERTHY SUPERVISION AND IS TRUE AND CORRECT TO THE BEST OF MY KNOWLEDGE AND BELIEF. THAT THERE ARE NO ENCROACHMENTS EXCEPT AS SHOWN HEREONOS M. JAMENEZ RECORDED IN VOLUME 10 PAGE 47 , PLAT RECORDS, EL PASO COUNTY, TX 1401 RANDOLPH STREET THE NORTH 15 FEET OF LOT 19, ALL OF LOT 20 AND THE SOUTH 5 FEET OF LOT 21, BLOCK 17 SECOND REVISED MAP OF SUNSET HEIGHTS CITY OF EL PASO. EL PASO COUNTY, TEXAS CONSULTING COMPANY 1790 LEE TREVING DRIVE SUITE 309 EL PASO, TEXAS 79936 (915) 633-6422

CARLOS M. JIMENEZ R.P.L.S. No. 3950

PHOTOGRAPHS



